810

TUNING FORK

Certificate of Accuracy

March 31, 2017

THIS IS TO CERTIFY THAT ON _____

TUNING FORK SERIAL NUMBER 227067 WAS TESTED

AND FOUND TO OSCILLATE AT 2615 CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 GHZ BAND TO

READ 25 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____

© Grant 4414

TUNING FORK

Certificate of Accuracy

March 31, 2017

THIS IS TO CERTIFY THAT ON _____

TUNING FORK SERIAL NUMBER 332609 WAS TESTED

AND FOUND TO OSCILLATE AT 4169 CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 GHZ BAND TO

READ 40 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____

© Grant 4414