


820

TUNING FORK
Certificate of Accuracy

April 4, 2017

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 241333 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 2614 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 _____ GHZ BAND TO
READ 25 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____ 


© 2005 0418

TUNING FORK
Certificate of Accuracy

April 4, 2017

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 348735 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 4166 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 _____ GHZ BAND TO
READ 40 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____ 

© 2005 0418