

T2

TUNING FORK  
**Certificate of Accuracy**

THIS IS TO CERTIFY THAT ON March 31, 2017  
TUNING FORK SERIAL NUMBER 160509 WAS TESTED  
AND FOUND TO OSCILLATE AT 2611 CYCLES PER SECOND.  
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 GHZ BAND TO  
READ 25 MPH.

**R & R RADAR, INC.**  
762 WHITE HORSE PIKE  
ATCO, N.J. 08004

SIGNED \_\_\_\_\_




© 2002 #416

TUNING FORK  
**Certificate of Accuracy**

THIS IS TO CERTIFY THAT ON March 31, 2017  
TUNING FORK SERIAL NUMBER 259872 WAS TESTED  
AND FOUND TO OSCILLATE AT 4167 CYCLES PER SECOND.  
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 GHZ BAND TO  
READ 40 MPH.

**R & R RADAR, INC.**  
762 WHITE HORSE PIKE  
ATCO, N.J. 08004

SIGNED \_\_\_\_\_



© 2002 #416